

SUSTAINABLE NAPIER COMMITTEE

Napier Civic Building 231 Hastings Street t+64 6 835 7579 e info@napier.govt.nz www.napier.govt.nz

Open Minutes Attachments


Meeting Date: Thursday 20 June 2024

Time: 9.30am – 11.21am

Venue: Large Exhibition Hall
War Memorial Centre
Marine Parade
Napier

TABLE OF CONTENTS


Item 2	Meeanee Awatoto Watermain	
Attachment 1	Meeanee Awatoto Watermain presentation (Doc Id 1670481)2	
Item 3	Bay View Water Main Pipeline Leak and Repair Update	
Attachment 1	Bay View Pipeline Break and Repair presentation (Doc Id 1770643)1	



Background

- The existing water source at Meeanee School and Community Hall is noncompliant.
- Various option were considered to provide water supply to Meeanee school and Community Center.
- After optioneering, this project combined with proposed Level of Service (LoS) upgrades at Te Awa.
- An extension of main to Meeanee speedway was added as part of the project (Sandy Road).









Pipe Decontamination





Figure 1: Watermains prior to Cyclone Gabriel (left) and post Cyclone Gabriel (right)

Decontamination process

- Flushing
- Foam swabbing
- Chlorination
- Flushing
- Storing and Testing



Key Dates

- June 2022: Pipe Purchased
- **February 2023**: Pipes contaminated from flooding
- September 2023: Construction Contract awarded to Drainways
- December 2023: Pipes disinfected, and construction started
- August 2024: Commissioning

Project Team

• Stantec : Design

Beca : Project and Contract Management

Drainways: Construction





Long Term Plan

- Water Supply to Awatoto Industrial Area.
- Water Supply to Meeanee Settlement Zone.




Questions.



Bay View Pipeline Break and Repair

June 2024





The Leak



Footage showing the exit point of the leak, into the estuary



The Position



Aerial view of where the break occurred





The Repair






10m lengths of PE pipe are welded together into a single 320m string

The Repair





A directional drilling rig is threaded down the broken pipe and used to drag the new section back through





Pressure Test



 The new section of pipe is pressure tested to ensure it meets our standards

Connection



Following disinfection, the new pipe section is connected to the network




Flushing



 The whole section of pipeline is flushed to ensure there was no contaminant entry during the break



Back online



The pipeline is returned to service, providing the primary supply feed to Bay View



